The Riley RM Centre Information Slip

Water manifold seals

The water manifold seals are thin as original and thicker to take account of the manifold sealing faces having been "cleaned up" over the years. With an original un modified water manifold the thick seals may be too thick to allow the studs RM20 to come fully through the manifold**,** whilst a heavily modified manifold fitted with the thin seals may foul the exhaust manifold preventing an effective water seal**.**

The Riley RM Centre Ltd

THE RILEY R.M. CENTRE LTD							
DRAWN	ISS	CHANGE	APP	DATE	NOTES	**Water manifold seals**	A4
SP	1			22/3/18			
						DWG NO. **Water manifold-IS**	SHEET 1